

**Photograph 10:** A 120mm anti-aircraft round, concrete filled. This round appears to have been part of a disposal detonation (notice the longitudinal cracks starting approximately three inches from the front of the round. These apparently were caused by the application of explosives. CMS explosively opened the item to confirm the filler was concrete).

